

Michigan SHPO Architectural Properties Identification Form



Property Overview and Location

Street Address	250 Washington				
City/Township, State, Zip Code	Grosse Pointe, MI 48230				
County	Wayne				
Assessor's Parcel #	37 005 08 0013 001				
Latitude/Longitude (to the 6 th decimal point)	Lat: 42.386575	Long: -82.90401			
Ownership	Private <input checked="" type="checkbox"/>	Public-Local <input type="checkbox"/>	Public-State <input type="checkbox"/>	Public-Federal <input type="checkbox"/>	Multiple <input type="checkbox"/>

Property Type

(Insert primary photograph below.)

Building <input checked="" type="checkbox"/> select sub-type below	Structure <input type="checkbox"/>
Commercial <input type="checkbox"/>	Object <input type="checkbox"/>
Residential <input checked="" type="checkbox"/>	
Industrial <input type="checkbox"/>	
Other <input type="checkbox"/>	



Architectural Information

Construction Date	1915
Architectural Style	Prairie Style
Building Form	L
Roof Form	Hip
Roof Materials	Asphalt Shingle
Exterior Wall Materials	Stucco
Foundation Materials	Concrete
Window Materials	Wood
Window Type	Double hung, Casement
Outbuildings	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Number/Type:	none

Eligibility

Individually Eligible	Criterion A <input type="checkbox"/>	Criterion B <input type="checkbox"/>	Criterion C <input type="checkbox"/>	Criterion D <input type="checkbox"/>		
Criteria Considerations:	a. <input type="checkbox"/> b. <input type="checkbox"/> c. <input type="checkbox"/> d. <input type="checkbox"/> e. <input type="checkbox"/> f. <input type="checkbox"/> g. <input type="checkbox"/>					
Component of a Historic District	Contributing to a district <input checked="" type="checkbox"/>	Non-contributing to a district <input type="checkbox"/>	Historic District Name			
Not Eligible <input type="checkbox"/>						
Area(s) of Significance	Social history, Architecture					
Period(s) of Significance	1898-1940					
Integrity – Does the property possess integrity in all or some of the 7 aspects?						
Location <input checked="" type="checkbox"/>	Design <input checked="" type="checkbox"/>	Materials <input checked="" type="checkbox"/>	Workmanship <input checked="" type="checkbox"/>	Setting <input checked="" type="checkbox"/>	Feeling <input checked="" type="checkbox"/>	Association <input type="checkbox"/>
General Integrity:	Intact <input checked="" type="checkbox"/>	Altered <input type="checkbox"/>	Moved <input type="checkbox"/>	Date(s):		
Historic Name						
Current/Common Name						
Historic/Original Owner	Edward P. Hammond					
Historic Building Use	D/Single Dwelling					
Current Building Use	D/Single Dwelling					
Architect/Engineer/Designer	Smith, Hinchman, & Grylls					
Builder/Contractor						

Survey Date	12/2020	Recorded By	J. Miller	Agency Report #	
-------------	---------	-------------	-----------	-----------------	--

For SHPO Use Only	SHPO Concurrence?: Y / N	Date:	
-------------------	--------------------------	-------	--

Narrative Architectural Description

Provide a detailed description of the property, including all character-defining features and any accessory resources. This is required for all properties.

A two-story asphalt shingled hip roof residence that features four shed roof dormers with a row of three windows each on the symmetrical east facade. The second story has ten 6-over-1 double-hung windows on the second floor. The first floor has eight floor-to-ceiling 8-over-6 windows. The dominant feature on the east façade is a windowed vestibule that projects from the main house. The vestibule features the same 8-over-6 windows on each side plus the main door with transom and side lights. It is crowned with a cornice with a row of modillions and a decorative metal balustrade. There is an access door to the balcony on the second floor. Three large brick chimneys are visible.

History of the Resource

Provide information on previous owners, land use(s), and construction and alteration dates in a narrative format. This is required for all intensive level surveys, NRPQs, and nominations, and recommended for other identification efforts.

Designed in 1915 by Smith, Hinchman, & Grylls for Edward P. Hammond, a graduate of the University of Michigan. He was the treasurer of the Federal Motor Truck Co. in Detroit and President of the Gemmer Manufacturing Co. (which made steering gears for the automotive industry).

Statement of Significance/Recommendation of Eligibility

Provide a detailed explanation of the property's eligibility for the National Register. Include an evaluation under at least one of the four National Register Criteria and one Area of Significance. Include a discussion of the seven aspects of integrity and make a recommendation about eligibility. This is required for all properties.

Constructed during the period of significance and retains historic and architectural integrity - contributes to the district

References

List references used to research and evaluate the individual property. For NRPQ's include copies of key documents.



Undated – courtesy of the Grosse Pointe Historical Society



Undated – courtesy of the Grosse Pointe Historical Society



undated – courtesy of the Grosse Pointe Historical Society



Undated – courtesy of the Grosse Pointe Historical Society



1951 – courtesy of the Grosse Pointe Historical Society



1980 – courtesy of the Grosse Pointe Historical Society

Michigan SHPO Architectural Properties Identification Form



Property Overview and Location

Street Address	270 Washington				
City/Township, State, Zip Code	Grosse Pointe, MI 48230				
County	Wayne				
Assessor's Parcel #	37 005 08 0013 002				
Latitude/Longitude (to the 6 th decimal point)	Lat: 42.386945	Long: -82.904189			
Ownership	Private <input checked="" type="checkbox"/>	Public-Local <input type="checkbox"/>	Public-State <input type="checkbox"/>	Public-Federal <input type="checkbox"/>	Multiple <input type="checkbox"/>

Property Type

(Insert primary photograph below.)

Building <input checked="" type="checkbox"/> select sub-type below	Structure <input type="checkbox"/>
Commercial <input type="checkbox"/>	Object <input type="checkbox"/>
Residential <input checked="" type="checkbox"/>	
Industrial <input type="checkbox"/>	
Other <input type="checkbox"/>	



Architectural Information

Construction Date	1915	
Architectural Style	Colonial Revival	
Building Form	Rectangular	
Roof Form	Side Gable	
Roof Materials	Asphalt Shingle	
Exterior Wall Materials	Brick, Wood Shingle	
Foundation Materials	Stone/Granite	
Window Materials	Wood	
Window Type	Double hung	
Outbuildings	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
Number/Type:	none	

Eligibility

Individually Eligible	Criterion A <input type="checkbox"/>	Criterion B <input type="checkbox"/>	Criterion C <input type="checkbox"/>	Criterion D <input type="checkbox"/>
Criteria Considerations:	a. <input type="checkbox"/> b. <input type="checkbox"/> c. <input type="checkbox"/> d. <input type="checkbox"/> e. <input type="checkbox"/> f. <input checked="" type="checkbox"/> g. <input type="checkbox"/>			
Component of a Historic District	Contributing to a district <input type="checkbox"/>	Non-contributing to a district <input checked="" type="checkbox"/>	Historic District Name	
Not Eligible <input type="checkbox"/>				
Area(s) of Significance	Social history, Architecture			
Period(s) of Significance	1898-1940			
Integrity – Does the property possess integrity in all or some of the 7 aspects?				
Location <input type="checkbox"/>	Design <input type="checkbox"/>	Materials <input type="checkbox"/>	Workmanship <input type="checkbox"/>	Setting <input type="checkbox"/> Feeling <input type="checkbox"/> Association <input type="checkbox"/>
General Integrity:	Intact <input type="checkbox"/>	Altered <input checked="" type="checkbox"/>	Moved <input type="checkbox"/>	Date(s):
Historic Name				
Current/Common Name				
Historic/Original Owner	Edward P. Hammond			
Historic Building Use	D/Single Dwelling			
Current Building Use	D/Single Dwelling			
Architect/Engineer/Designer	Smith, Hinchman, & Grylls			
Builder/Contractor				

Survey Date	12/2020	Recorded By	J. Miller	Agency Report #	
-------------	---------	-------------	-----------	-----------------	--

For SHPO Use Only	SHPO Concurrence?: Y / N	Date:	
-------------------	--------------------------	-------	--

Narrative Architectural Description

Provide a detailed description of the property, including all character-defining features and any accessory resources. This is required for all properties.

A cut stone two-story asphalt shingled side gable Colonial Revival with exposed rafter tails and flared eaves. The main façade shows a line of eight 8-over-8 double-hung windows on the second floor and a single, two doubles and a French door on the main level. A full-length hip roof porch is supported by seven wooden posts. There is a shed roof dormer on the rear of the house. There is a louver in the middle of the roof with a ball and a bird on top of it.

History of the Resource

Provide information on previous owners, land use(s), and construction and alteration dates in a narrative format. This is required for all intensive level surveys, NRPQs, and nominations, and recommended for other identification efforts.

Designed in 1915 by Smith, Hinchman, & Grylls for Edward P. Hammond, a graduate of the University of Michigan. He was the treasurer of the Federal Motor Truck Co. in Detroit and President of the Gemmer Manufacturing Co. (which made steering gears for the automotive industry). This house was originally the garage for 250 Washington.

Statement of Significance/Recommendation of Eligibility

Provide a detailed explanation of the property's eligibility for the National Register. Include an evaluation under at least one of the four National Register Criteria and one Area of Significance. Include a discussion of the seven aspects of integrity and make a recommendation about eligibility. This is required for all properties.

This house no longer retains its original appearance or historic integrity and is non-contributing to the historic district.

References

List references used to research and evaluate the individual property. For NRPQ's include copies of key documents.



Undated – courtesy of the Grosse Pointe Historical Society

Michigan SHPO Architectural Properties Identification Form



Property Overview and Location

Street Address	281 Washington				
City/Township, State, Zip Code	Grosse Pointe, MI 48230				
County	Wayne				
Assessor's Parcel #	37 005 13 0001 000				
Latitude/Longitude (to the 6 th decimal point)	Lat: 42.386962	Long: -82.904531			
Ownership	Private <input checked="" type="checkbox"/>	Public-Local <input type="checkbox"/>	Public-State <input type="checkbox"/>	Public-Federal <input type="checkbox"/>	Multiple <input type="checkbox"/>

Property Type

(Insert primary photograph below.)

Building <input checked="" type="checkbox"/> select sub-type below	Structure <input type="checkbox"/>
Commercial <input type="checkbox"/>	Object <input type="checkbox"/>
Residential <input checked="" type="checkbox"/>	
Industrial <input type="checkbox"/>	
Other <input type="checkbox"/>	



Architectural Information

Construction Date	1979
Architectural Style	Neo-Colonial
Building Form	L
Roof Form	Gable Ell
Roof Materials	Asphalt Shingle
Exterior Wall Materials	Brick, Horizontal Siding
Foundation Materials	Brick
Window Materials	Wood
Window Type	Double hung
Outbuildings	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Number/Type:	none

Eligibility

Individually Eligible	Criterion A <input type="checkbox"/>	Criterion B <input type="checkbox"/>	Criterion C <input type="checkbox"/>	Criterion D <input type="checkbox"/>
Criteria Considerations:	a. <input type="checkbox"/> b. <input type="checkbox"/> c. <input type="checkbox"/> d. <input type="checkbox"/> e. <input type="checkbox"/> f. <input type="checkbox"/> g. <input type="checkbox"/>			
Component of a Historic District	Contributing to a district <input type="checkbox"/>	Non-contributing to a district <input checked="" type="checkbox"/>	Historic District Name	
Not Eligible <input type="checkbox"/>				
Area(s) of Significance	Social history, Architecture			
Period(s) of Significance	1898-1940			
Integrity – Does the property possess integrity in all or some of the 7 aspects?				
Location <input type="checkbox"/>	Design <input type="checkbox"/>	Materials <input type="checkbox"/>	Workmanship <input type="checkbox"/>	Setting <input type="checkbox"/> Feeling <input type="checkbox"/> Association <input type="checkbox"/>
General Integrity:	Intact <input type="checkbox"/>	Altered <input type="checkbox"/>	Moved <input type="checkbox"/>	Date(s):
Historic Name				
Current/Common Name				
Historic/Original Owner				
Historic Building Use	D/Single Dwelling			
Current Building Use	D/Single Dwelling			
Architect/Engineer/Designer				
Builder/Contractor				

Survey Date	12/2020	Recorded By	J. Miller	Agency Report #	
-------------	---------	-------------	-----------	-----------------	--

For SHPO Use Only	SHPO Concurrence?: Y / N	Date:	
-------------------	--------------------------	-------	--

Narrative Architectural Description

Provide a detailed description of the property, including all character-defining features and any accessory resources. This is required for all properties.

A two-story ell shaped neo-Colonial with an asphalt shingled gable roof. The upper floor slightly overhangs and is sheathed in aluminum siding. The main floor is covered in brick in a running bond pattern. A dual-pitched side gabled shed roof projects from the west façade and features a large brick chimney. The roof covers a full-width front porch supported by 5 wooden posts. Windows are a mix of casement and double-hung.

History of the Resource

Provide information on previous owners, land use(s), and construction and alteration dates in a narrative format. This is required for all intensive level surveys, NRPQs, and nominations, and recommended for other identification efforts.

Statement of Significance/Recommendation of Eligibility

Provide a detailed explanation of the property's eligibility for the National Register. Include an evaluation under at least one of the four National Register Criteria and one Area of Significance. Include a discussion of the seven aspects of integrity and make a recommendation about eligibility. This is required for all properties.

This house is outside of the period of significance and is non-contributing to the historic district..

References

List references used to research and evaluate the individual property. For NRPQ's include copies of key documents.



Undated – courtesy of the Grosse Pointe Historical Society



1980 – courtesy of the Grosse Pointe Historical Society

Michigan SHPO Architectural Properties Identification Form



Property Overview and Location

Street Address	285 Washington				
City/Township, State, Zip Code	Grosse Pointe, MI 48230				
County	Wayne				
Assessor's Parcel #	37 005 13 0006 300				
Latitude/Longitude (to the 6 th decimal point)	Lat: 42.387034	Long: -82.904566			
Ownership	Private <input checked="" type="checkbox"/>	Public-Local <input type="checkbox"/>	Public-State <input type="checkbox"/>	Public-Federal <input type="checkbox"/>	Multiple <input type="checkbox"/>

Property Type

(Insert primary photograph below.)

Building <input checked="" type="checkbox"/> select sub-type below	Structure <input type="checkbox"/>
Commercial <input type="checkbox"/>	Object <input type="checkbox"/>
Residential <input checked="" type="checkbox"/>	
Industrial <input type="checkbox"/>	
Other <input type="checkbox"/>	



Architectural Information

Construction Date	1910
Architectural Style	Italian Renaissance
Building Form	Rectangular
Roof Form	Hip
Roof Materials	Asphalt Shingle
Exterior Wall Materials	Brick
Foundation Materials	Brick
Window Materials	Wood
Window Type	Double hung, Casement
Outbuildings	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Number/Type:	garage

Eligibility

Individually Eligible	Criterion A <input type="checkbox"/>	Criterion B <input type="checkbox"/>	Criterion C <input type="checkbox"/>	Criterion D <input type="checkbox"/>		
Criteria Considerations:	a. <input type="checkbox"/> b. <input type="checkbox"/> c. <input type="checkbox"/> d. <input type="checkbox"/> e. <input type="checkbox"/> f. <input type="checkbox"/> g. <input type="checkbox"/>					
Component of a Historic District	Contributing to a district <input checked="" type="checkbox"/>	Non-contributing to a district <input type="checkbox"/>	Historic District Name			
Not Eligible <input type="checkbox"/>						
Area(s) of Significance	Social history, Architecture					
Period(s) of Significance	1898-1940					
Integrity – Does the property possess integrity in all or some of the 7 aspects?						
Location <input checked="" type="checkbox"/>	Design <input checked="" type="checkbox"/>	Materials <input checked="" type="checkbox"/>	Workmanship <input checked="" type="checkbox"/>	Setting <input checked="" type="checkbox"/>	Feeling <input checked="" type="checkbox"/>	Association <input checked="" type="checkbox"/>
General Integrity:	Intact <input checked="" type="checkbox"/>	Altered <input type="checkbox"/>	Moved <input type="checkbox"/>	Date(s):		
Historic Name						
Current/Common Name						
Historic/Original Owner						
Historic Building Use	D/Single Dwelling					
Current Building Use	D/Single Dwelling					
Architect/Engineer/Designer	Louis Kamper					
Builder/Contractor						

Survey Date	12/2020	Recorded By	J. Miller	Agency Report #	
-------------	---------	-------------	-----------	-----------------	--

For SHPO Use Only	SHPO Concurrence?: Y / N	Date:	
-------------------	--------------------------	-------	--

Narrative Architectural Description

Provide a detailed description of the property, including all character-defining features and any accessory resources. This is required for all properties.

An asphalt shingled hip roof Prairie style with wide overhanging eaves supported by elaborate brackets. There is a shed roof dormer with a ribbon of three double-hung windows on the north elevation. The upper floor has five double-hung windows with limestone lintels and sills placed symmetrically above the main entrance. The lower level has a row of three pair of French doors with transoms and a balconet with metal decorative balustrade. There is a pergola-like structure projecting from the façade above the French doors. Two double-hung windows with limestone lintels and sills are on the opposite side of the door. Two French doors are recessed in a round arched casing between two Doric columns supporting a large cornice. A round arched window with a corresponding row of arched side lights is above the door. The French door/transom/balconet/pergola combination is repeated on the north end of the east façade. There is a conical roof on a two-story bay window with wide overhanging eave and brackets centrally located on the east façade. The upper bay has double-hung windows while the lower has French doors with round arched fan lights. A massive portico supported by eight Doric columns covers this side entry. There is a low spindled balustrade around the outside of the porch.

Matching two-story detached garage at northwest corner of property contributes to the district.

History of the Resource

Provide information on previous owners, land use(s), and construction and alteration dates in a narrative format. This is required for all intensive level surveys, NRPQs, and nominations, and recommended for other identification efforts.

Designed by Louis Kamper in 1918.

Statement of Significance/Recommendation of Eligibility

Provide a detailed explanation of the property's eligibility for the National Register. Include an evaluation under at least one of the four National Register Criteria and one Area of Significance. Include a discussion of the seven aspects of integrity and make a recommendation about eligibility. This is required for all properties.

Constructed during the period of significance and retains historic and architectural integrity - contributes to the district

References

List references used to research and evaluate the individual property. For NRPQ's include copies of key documents.



Undated – courtesy of the Grosse Pointe Historical Society



1972 – courtesy of the Grosse Pointe Historical Society

Michigan SHPO Architectural Properties Identification Form



Property Overview and Location

Street Address	295 Washington				
City/Township, State, Zip Code	Grosse Pointe, MI 48230				
County	Wayne				
Assessor's Parcel #	37 005 08 0029 306				
Latitude/Longitude (to the 6 th decimal point)	Lat: 42.387215	Long: -82.904653			
Ownership	Private <input checked="" type="checkbox"/>	Public-Local <input type="checkbox"/>	Public-State <input type="checkbox"/>	Public-Federal <input type="checkbox"/>	Multiple <input type="checkbox"/>

Property Type

(Insert primary photograph below.)

Building <input checked="" type="checkbox"/> select sub-type below	Structure <input type="checkbox"/>
Commercial <input type="checkbox"/>	Object <input type="checkbox"/>
Residential <input checked="" type="checkbox"/>	
Industrial <input type="checkbox"/>	
Other <input type="checkbox"/>	



Architectural Information

Construction Date	1959	
Architectural Style	Neo-Colonial	
Building Form	Irregular	
Roof Form	Hip	
Roof Materials	Asphalt Shingle	
Exterior Wall Materials	Brick	
Foundation Materials	Brick	
Window Materials	Wood	
Window Type	Double hung	
Outbuildings	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
Number/Type:	none	

Eligibility

Individually Eligible	Criterion A <input type="checkbox"/>	Criterion B <input type="checkbox"/>	Criterion C <input type="checkbox"/>	Criterion D <input type="checkbox"/>
Criteria Considerations:	a. <input type="checkbox"/> b. <input type="checkbox"/> c. <input type="checkbox"/> d. <input type="checkbox"/> e. <input type="checkbox"/> f. <input type="checkbox"/> g. <input type="checkbox"/>			
Component of a Historic District	Contributing to a district <input type="checkbox"/>	Non-contributing to a district <input checked="" type="checkbox"/>	Historic District Name	
Not Eligible <input type="checkbox"/>				
Area(s) of Significance	Social history, Architecture			
Period(s) of Significance	1898-1940			
Integrity – Does the property possess integrity in all or some of the 7 aspects?				
Location <input type="checkbox"/>	Design <input type="checkbox"/>	Materials <input type="checkbox"/>	Workmanship <input type="checkbox"/>	Setting <input type="checkbox"/> Feeling <input type="checkbox"/> Association <input type="checkbox"/>
General Integrity:	Intact <input checked="" type="checkbox"/>	Altered <input type="checkbox"/>	Moved <input type="checkbox"/>	Date(s):
Historic Name				
Current/Common Name				
Historic/Original Owner				
Historic Building Use	D/Single Dwelling			
Current Building Use	D/Single Dwelling			
Architect/Engineer/Designer				
Builder/Contractor				

Survey Date	12/2020	Recorded By	J. Miller	Agency Report #	
-------------	---------	-------------	-----------	-----------------	--

For SHPO Use Only	SHPO Concurrence?: Y / N	Date:	
-------------------	--------------------------	-------	--

Narrative Architectural Description

Provide a detailed description of the property, including all character-defining features and any accessory resources. This is required for all properties.

An asphalt shingled triple hip roof brick neo-Colonial brick quoins on the corners. The two-story house has a line of modillions runs under the entire roofline. All windows visible are double hung with louvered shutters. A balconet with metal balustrade is featured in two places on the north face of two wings of the house. A two-car garage is located on the west façade of the ground floor of the northern wing. A segmental arched French is crowned by a row of bricks. A large chimney is on the west façade.

History of the Resource

Provide information on previous owners, land use(s), and construction and alteration dates in a narrative format. This is required for all intensive level surveys, NRPQs, and nominations, and recommended for other identification efforts.

Statement of Significance/Recommendation of Eligibility

Provide a detailed explanation of the property's eligibility for the National Register. Include an evaluation under at least one of the four National Register Criteria and one Area of Significance. Include a discussion of the seven aspects of integrity and make a recommendation about eligibility. This is required for all properties.

This house is outside of the period of significance and is non-contributing to the historic district.

References

List references used to research and evaluate the individual property. For NRPQ's include copies of key documents.



Undated – courtesy of the Grosse Pointe Historical Society

Michigan SHPO Architectural Properties Identification Form



Property Overview and Location

Street Address	300 Washington				
City/Township, State, Zip Code	Grosse Pointe, MI 48230				
County	Wayne				
Assessor's Parcel #	37 005 08 0014 000				
Latitude/Longitude (to the 6 th decimal point)	Lat: 42.387501	Long: -82.904458			
Ownership	Private <input checked="" type="checkbox"/>	Public-Local <input type="checkbox"/>	Public-State <input type="checkbox"/>	Public-Federal <input type="checkbox"/>	Multiple <input type="checkbox"/>

Property Type

(Insert primary photograph below.)

Building <input checked="" type="checkbox"/> select sub-type below	Structure <input type="checkbox"/>
Commercial <input type="checkbox"/>	Object <input type="checkbox"/>
Residential <input checked="" type="checkbox"/>	
Industrial <input type="checkbox"/>	
Other <input type="checkbox"/>	



Architectural Information

Construction Date	1919	
Architectural Style	Colonial Revival	
Building Form	Irregular	
Roof Form	Hip	
Roof Materials	Asphalt Shingle	
Exterior Wall Materials	Stucco	
Foundation Materials	Concrete	
Window Materials	Wood	
Window Type	Double hung	
Outbuildings	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
Number/Type:	garage	

Eligibility

Individually Eligible	Criterion A <input type="checkbox"/>	Criterion B <input type="checkbox"/>	Criterion C <input type="checkbox"/>	Criterion D <input type="checkbox"/>		
Criteria Considerations:	a. <input type="checkbox"/> b. <input type="checkbox"/> c. <input type="checkbox"/> d. <input type="checkbox"/> e. <input type="checkbox"/> f. <input type="checkbox"/> g. <input type="checkbox"/>					
Component of a Historic District	Contributing to a district <input checked="" type="checkbox"/>	Non-contributing to a district <input type="checkbox"/>	Historic District Name			
Not Eligible <input type="checkbox"/>						
Area(s) of Significance	Social history, Architecture					
Period(s) of Significance	1898-1940					
Integrity – Does the property possess integrity in all or some of the 7 aspects?						
Location <input checked="" type="checkbox"/>	Design <input checked="" type="checkbox"/>	Materials <input checked="" type="checkbox"/>	Workmanship <input checked="" type="checkbox"/>	Setting <input checked="" type="checkbox"/>	Feeling <input checked="" type="checkbox"/>	Association <input type="checkbox"/>
General Integrity:	Intact <input checked="" type="checkbox"/>	Altered <input type="checkbox"/>	Moved <input type="checkbox"/>	Date(s):		
Historic Name						
Current/Common Name						
Historic/Original Owner						
Historic Building Use	D/Single Dwelling					
Current Building Use	D/Single Dwelling					
Architect/Engineer/Designer						
Builder/Contractor						

Survey Date	12/2020	Recorded By	J. Miller	Agency Report #	
-------------	---------	-------------	-----------	-----------------	--

For SHPO Use Only	SHPO Concurrence?: Y / N	Date:	
-------------------	--------------------------	-------	--

Narrative Architectural Description

Provide a detailed description of the property, including all character-defining features and any accessory resources. This is required for all properties.

A two-story Colonial Revival with an asphalt shingled hip roof with overhanging eaves. A two-story round tower with a conical roof is the dominant feature of the main elevation. The tower features 4-over-4 windows that feature segmental arches. The main entrance is next to the tower and features an overhanging cornice supported by brackets. The rectangular door has a transom window above it. Next to the main entry is a slightly protruding pavilion with a metal roof and four windows. All visible windows appear to be double hung. Three massive chimneys are visible.

Matching two-story detached garage contributes to property.

History of the Resource

Provide information on previous owners, land use(s), and construction and alteration dates in a narrative format. This is required for all intensive level surveys, NRPQs, and nominations, and recommended for other identification efforts.

It appears that the original door hood which was arched was changed to a non-matching flat hood.

Statement of Significance/Recommendation of Eligibility

Provide a detailed explanation of the property's eligibility for the National Register. Include an evaluation under at least one of the four National Register Criteria and one Area of Significance. Include a discussion of the seven aspects of integrity and make a recommendation about eligibility. This is required for all properties.

Constructed during the period of significance and retains historic and architectural integrity - contributes to the district.

References

List references used to research and evaluate the individual property. For NRPQ's include copies of key documents.



Undated – courtesy of the Grosse Pointe Historical Society



1966 – courtesy of the Grosse Pointe Historical Society



1967 – courtesy of the Grosse Pointe Historical Society

Michigan SHPO Architectural Properties Identification Form



Property Overview and Location

Street Address	305 Washington				
City/Township, State, Zip Code	Grosse Pointe, MI 48230				
County	Wayne				
Assessor's Parcel #	37 005 08 0029 003				
Latitude/Longitude (to the 6 th decimal point)	Lat: 42.387395	Long: -82.904741			
Ownership	Private <input checked="" type="checkbox"/>	Public-Local <input type="checkbox"/>	Public-State <input type="checkbox"/>	Public-Federal <input type="checkbox"/>	Multiple <input type="checkbox"/>

Property Type

(Insert primary photograph below.)

Building <input checked="" type="checkbox"/> select sub-type below	Structure <input type="checkbox"/>
Commercial <input type="checkbox"/>	Object <input type="checkbox"/>
Residential <input checked="" type="checkbox"/>	
Industrial <input type="checkbox"/>	
Other <input type="checkbox"/>	



Architectural Information

Construction Date	1977
Architectural Style	Neo-Colonial
Building Form	Rectangular
Roof Form	Hip
Roof Materials	Asphalt Shingle
Exterior Wall Materials	Brick
Foundation Materials	Brick
Window Materials	Wood
Window Type	Double hung
Outbuildings	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Number/Type:	none

Eligibility

Individually Eligible	Criterion A <input type="checkbox"/>	Criterion B <input type="checkbox"/>	Criterion C <input type="checkbox"/>	Criterion D <input type="checkbox"/>
Criteria Considerations:	a. <input type="checkbox"/> b. <input type="checkbox"/> c. <input type="checkbox"/> d. <input type="checkbox"/> e. <input type="checkbox"/> f. <input type="checkbox"/> g. <input type="checkbox"/>			
Component of a Historic District	Contributing to a district <input type="checkbox"/>	Non-contributing to a district <input checked="" type="checkbox"/>	Historic District Name	
Not Eligible <input type="checkbox"/>				
Area(s) of Significance	Social history, Architecture			
Period(s) of Significance	1898-1940			
Integrity – Does the property possess integrity in all or some of the 7 aspects?				
Location <input type="checkbox"/>	Design <input type="checkbox"/>	Materials <input type="checkbox"/>	Workmanship <input type="checkbox"/>	Setting <input type="checkbox"/> Feeling <input type="checkbox"/> Association <input type="checkbox"/>
General Integrity:	Intact <input checked="" type="checkbox"/>	Altered <input type="checkbox"/>	Moved <input type="checkbox"/>	Date(s):
Historic Name				
Current/Common Name				
Historic/Original Owner				
Historic Building Use	D/Single Dwelling			
Current Building Use	D/Single Dwelling			
Architect/Engineer/Designer				
Builder/Contractor				

Survey Date	12/2020	Recorded By	J. Miller	Agency Report #	
-------------	---------	-------------	-----------	-----------------	--

For SHPO Use Only	SHPO Concurrence?: Y / N	Date:	
-------------------	--------------------------	-------	--

Narrative Architectural Description

Provide a detailed description of the property, including all character-defining features and any accessory resources. This is required for all properties.

A brick two-story neo-Colonial with an asphalt shingled hip roof with a wide overhang supported by 6 wooden posts. The symmetrical main elevation features five evenly spaced 6-over-6 double hung windows on the upper level. The lower has four 9-over-9 double hung windows, two on either side of the centrally located main entry. The main entry has five side lights on either side of the door. All windows on the main elevation have louvered shutters. The east façade features an intersecting one-story hip roof garage with two 6-over-6 double hung windows.

History of the Resource

Provide information on previous owners, land use(s), and construction and alteration dates in a narrative format. This is required for all intensive level surveys, NRPQs, and nominations, and recommended for other identification efforts.

Statement of Significance/Recommendation of Eligibility

Provide a detailed explanation of the property's eligibility for the National Register. Include an evaluation under at least one of the four National Register Criteria and one Area of Significance. Include a discussion of the seven aspects of integrity and make a recommendation about eligibility. This is required for all properties.

This house is outside of the period of significance and is non-contributing to the historic district.

References

List references used to research and evaluate the individual property. For NRPQ's include copies of key documents.



1978 – courtesy of the Grosse Pointe Historical Society



1980 – courtesy of the Grosse Pointe Historical Society

Michigan SHPO Architectural Properties Identification Form



Property Overview and Location

Street Address	315 Washington				
City/Township, State, Zip Code	Grosse Pointe, MI 48230				
County	Wayne				
Assessor's Parcel #	37 005 08 0028 002				
Latitude/Longitude (to the 6 th decimal point)	Lat: 42.387576	Long: -82.904828			
Ownership	Private <input checked="" type="checkbox"/>	Public-Local <input type="checkbox"/>	Public-State <input type="checkbox"/>	Public-Federal <input type="checkbox"/>	Multiple <input type="checkbox"/>

Property Type

(Insert primary photograph below.)

Building <input checked="" type="checkbox"/> select sub-type below	Structure <input type="checkbox"/>
Commercial <input type="checkbox"/>	Object <input type="checkbox"/>
Residential <input checked="" type="checkbox"/>	
Industrial <input type="checkbox"/>	
Other <input type="checkbox"/>	



Architectural Information

Construction Date	1923	
Architectural Style	Tudor	
Building Form	Irregular	
Roof Form	Hip	
Roof Materials	Slate	
Exterior Wall Materials	Brick	
Foundation Materials	Brick	
Window Materials	Metal	
Window Type	Casement	
Outbuildings	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
Number/Type:	garage	

Eligibility

Individually Eligible	Criterion A <input type="checkbox"/>	Criterion B <input type="checkbox"/>	Criterion C <input type="checkbox"/>	Criterion D <input type="checkbox"/>		
Criteria Considerations:	a. <input type="checkbox"/> b. <input type="checkbox"/> c. <input type="checkbox"/> d. <input type="checkbox"/> e. <input type="checkbox"/> f. <input type="checkbox"/> g. <input type="checkbox"/>					
Component of a Historic District	Contributing to a district <input checked="" type="checkbox"/>	Non-contributing to a district <input type="checkbox"/>	Historic District Name			
Not Eligible <input type="checkbox"/>						
Area(s) of Significance	Social history, Architecture					
Period(s) of Significance	1898-1940					
Integrity – Does the property possess integrity in all or some of the 7 aspects?						
Location <input checked="" type="checkbox"/>	Design <input checked="" type="checkbox"/>	Materials <input checked="" type="checkbox"/>	Workmanship <input checked="" type="checkbox"/>	Setting <input checked="" type="checkbox"/>	Feeling <input checked="" type="checkbox"/>	Association <input checked="" type="checkbox"/>
General Integrity:	Intact <input checked="" type="checkbox"/>	Altered <input type="checkbox"/>	Moved <input type="checkbox"/>	Date(s):		
Historic Name	Ralph Harmon Booth House					
Current/Common Name						
Historic/Original Owner	Ralph Harmon Booth					
Historic Building Use	D/Single Dwelling					
Current Building Use	D/Single Dwelling					
Architect/Engineer/Designer	Marcus Burrowes					
Builder/Contractor						

Survey Date	12/2020	Recorded By	J. Miller	Agency Report #	
-------------	---------	-------------	-----------	-----------------	--

For SHPO Use Only	SHPO Concurrence?: Y / N	Date:	
-------------------	--------------------------	-------	--

Narrative Architectural Description

Provide a detailed description of the property, including all character-defining features and any accessory resources. This is required for all properties.

A two-story neo-Tudor with a slate hip roof. The main elevation has two projecting gable wall dormers with a gable window and a band of five casement windows with transoms on both the first and second floors. Between the two wall dormers are two shed roof dormers. The main entrance is centered between the roof dormers and features an impressive limestone surround, with twisted baroque columns and a central bracket supporting a massive cornice. The cornice features four rosettes on the frieze. Directly above the main entrance is a collection of nine windows with nine panes each. A large brick chimney is visible in the southwest corner, another in the northeast corner. A massive brick stack of chimneys rises above the west end of the house. Gutters and downspouts appear to be copper with rainwater heads. All visible windows are leaded glass with limestone sills, casings, and lintels. A brick wing with a side gable projects from the west façade and features a front facing gable wall dormer with several windows.

A garage is found to the rear of the house on the west end. The garage is of a similar construction and style as the main house and contributes to the district.

The brick and stone wall contributes to the district/property.

History of the Resource

Provide information on previous owners, land use(s), and construction and alteration dates in a narrative format. This is required for all intensive level surveys, NRPQs, and nominations, and recommended for other identification efforts.

Built in 1923 for Ralph Harmon Booth, president of Booth newspapers, by Marcus Burrowes. Rose garden and terraces designed by Leonard B. Willeke in the 1940's. Booth was influential in the creation of the Detroit Institute of Arts (1922-1927).

Statement of Significance/Recommendation of Eligibility

Provide a detailed explanation of the property's eligibility for the National Register. Include an evaluation under at least one of the four National Register Criteria and one Area of Significance. Include a discussion of the seven aspects of integrity and make a recommendation about eligibility. This is required for all properties.

Constructed during the period of significance, has strong historic and architectural associations, retains historic and architectural integrity - contributes to the district

References

List references used to research and evaluate the individual property. For NRPQ's include copies of key documents.

Blog post by Ms. Katie Doelle for the Higbie Maxon Agney realty company, April 15, 2019
<https://www.higbiemaxon.com/blog/315-washington-aka-the-ralph-harmon-booth-house.html>

Photos courtesy of the Grosse Pointe Historical Society – top 1969, others undated





October 2020

Michigan SHPO Architectural Properties Identification Form



Property Overview and Location

Street Address	320 Washington				
City/Township, State, Zip Code	Grosse Pointe, MI 48230				
County	Wayne				
Assessor's Parcel #	37 005 08 0015 000				
Latitude/Longitude (to the 6 th decimal point)	Lat: 42.387871	Long: -82.904638			
Ownership	Private <input checked="" type="checkbox"/>	Public-Local <input type="checkbox"/>	Public-State <input type="checkbox"/>	Public-Federal <input type="checkbox"/>	Multiple <input type="checkbox"/>

Property Type

(Insert primary photograph below.)

Building <input checked="" type="checkbox"/> select sub-type below	Structure <input type="checkbox"/>
Commercial <input type="checkbox"/>	Object <input type="checkbox"/>
Residential <input checked="" type="checkbox"/>	
Industrial <input type="checkbox"/>	
Other <input type="checkbox"/>	



Architectural Information

Construction Date	1920	
Architectural Style	Colonial Revival	
Building Form	Rectangular	
Roof Form	Hip	
Roof Materials	Slate	
Exterior Wall Materials	Brick	
Foundation Materials	Brick	
Window Materials	Wood	
Window Type	Double hung	
Outbuildings	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
Number/Type:	garage	

Eligibility

Individually Eligible	Criterion A <input type="checkbox"/>	Criterion B <input type="checkbox"/>	Criterion C <input type="checkbox"/>	Criterion D <input type="checkbox"/>		
Criteria Considerations:	a. <input type="checkbox"/> b. <input type="checkbox"/> c. <input type="checkbox"/> d. <input type="checkbox"/> e. <input type="checkbox"/> f. <input type="checkbox"/> g. <input type="checkbox"/>					
Component of a Historic District	Contributing to a district <input checked="" type="checkbox"/>	Non-contributing to a district <input type="checkbox"/>	Historic District Name			
Not Eligible <input type="checkbox"/>						
Area(s) of Significance	Social history, Architecture					
Period(s) of Significance	1898-1940					
Integrity – Does the property possess integrity in all or some of the 7 aspects?						
Location <input checked="" type="checkbox"/>	Design <input checked="" type="checkbox"/>	Materials <input checked="" type="checkbox"/>	Workmanship <input checked="" type="checkbox"/>	Setting <input checked="" type="checkbox"/>	Feeling <input checked="" type="checkbox"/>	Association <input checked="" type="checkbox"/>
General Integrity:	Intact <input checked="" type="checkbox"/>	Altered <input type="checkbox"/>	Moved <input type="checkbox"/>	Date(s):		
Historic Name						
Current/Common Name						
Historic/Original Owner	James S. Holden					
Historic Building Use	D/Single Dwelling					
Current Building Use	D/Single Dwelling					
Architect/Engineer/Designer	Crombie & Stanton					
Builder/Contractor						

Survey Date	12/2020	Recorded By	J. Miller	Agency Report #	
-------------	---------	-------------	-----------	-----------------	--

For SHPO Use Only	SHPO Concurrence?: Y / N	Date:	
-------------------	--------------------------	-------	--

Narrative Architectural Description

Provide a detailed description of the property, including all character-defining features and any accessory resources. This is required for all properties.

A symmetrical Colonial Revival house with a slate hip roof with flared eaves. Two pyramidal roof cross gables project from the main elevation. Each cross gable has a row of dentils on the frieze. Windows appear to be double-hung in a 6-over-6 pattern on the upper story and 6-over-9 on the lower. There is a brick belt course and brick quoins on the corners. The central part of the house features a row of dentils on the frieze plus an upper and a lower window on either side of the main entry. The four panel round arched door features a sunburst pattern in the arch. The door is recessed from pilasters topped with a round arch with a keystone bracket. Two columns support a wide cornice with the row of dentils. A 6-over-6 window framed in limestone is above the cornice. There is a limestone hood over the top of the window limestone tabs along the sides. Three massive brick chimneys are visible.

A matching detached garage contributes to the district.

A wall on the north property line contributes to the district.

History of the Resource

Provide information on previous owners, land use(s), and construction and alteration dates in a narrative format. This is required for all intensive level surveys, NRPQs, and nominations, and recommended for other identification efforts.

Designed by Crombie & Stanton in 1920 for a James S. Holden. James Stansbury Holden was a prominent Detroit real estate man, banker and philanthropist, president and director of the James S. Holden Co. and Grand Lawn Cemetery, Detroit, and held executive positions with Holden Reaume Co., Parke-Davis and Co., Detroit Edison Co., Burroughs Adding Machine Co., and the National Bank of Detroit, among other concerns.

Statement of Significance/Recommendation of Eligibility

Provide a detailed explanation of the property's eligibility for the National Register. Include an evaluation under at least one of the four National Register Criteria and one Area of Significance. Include a discussion of the seven aspects of integrity and make a recommendation about eligibility. This is required for all properties.

Constructed during the period of significance and retains historic and architectural integrity - contributes to the district.

References

List references used to research and evaluate the individual property. For NRPQ's include copies of key documents.



undated – courtesy of the Grosse Pointe Historical Society



undated – courtesy of the Grosse Pointe Historical Society



undated – courtesy of the Grosse Pointe Historical Society



undated – courtesy of the Grosse Pointe Historical Society

Michigan SHPO Architectural Properties Identification Form



Property Overview and Location

Street Address	333 Washington				
City/Township, State, Zip Code	Grosse Pointe, MI 48230				
County	Wayne				
Assessor's Parcel #	37 005 08 0028 001				
Latitude/Longitude (to the 6 th decimal point)	Lat: 42.3879	Long: -82.904985			
Ownership	Private <input checked="" type="checkbox"/>	Public-Local <input type="checkbox"/>	Public-State <input type="checkbox"/>	Public-Federal <input type="checkbox"/>	Multiple <input type="checkbox"/>

Property Type

(Insert primary photograph below.)

Building <input checked="" type="checkbox"/> select sub-type below	Structure <input type="checkbox"/>
Commercial <input type="checkbox"/>	Object <input type="checkbox"/>
Residential <input checked="" type="checkbox"/>	
Industrial <input type="checkbox"/>	
Other <input type="checkbox"/>	



Architectural Information

Construction Date	1912	
Architectural Style	French Eclectic	
Building Form	Irregular	
Roof Form	Hip	
Roof Materials	Slate	
Exterior Wall Materials	Stucco	
Foundation Materials	Concrete	
Window Materials	Wood	
Window Type	Casement	
Outbuildings	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
Number/Type:	garage	

Eligibility

Individually Eligible	Criterion A <input type="checkbox"/>	Criterion B <input type="checkbox"/>	Criterion C <input type="checkbox"/>	Criterion D <input type="checkbox"/>		
Criteria Considerations:	a. <input type="checkbox"/> b. <input type="checkbox"/> c. <input type="checkbox"/> d. <input type="checkbox"/> e. <input type="checkbox"/> f. <input type="checkbox"/> g. <input type="checkbox"/>					
Component of a Historic District	Contributing to a district <input type="checkbox"/>	Non-contributing to a district <input checked="" type="checkbox"/>	Historic District Name			
Not Eligible <input type="checkbox"/>						
Area(s) of Significance	Social history, Architecture					
Period(s) of Significance	1898-1940					
Integrity – Does the property possess integrity in all or some of the 7 aspects?						
Location <input checked="" type="checkbox"/>	Design <input type="checkbox"/>	Materials <input checked="" type="checkbox"/>	Workmanship <input type="checkbox"/>	Setting <input checked="" type="checkbox"/>	Feeling <input checked="" type="checkbox"/>	Association <input checked="" type="checkbox"/>
General Integrity:	Intact <input type="checkbox"/>	Altered <input checked="" type="checkbox"/>	Moved <input type="checkbox"/>	Date(s):		
Historic Name						
Current/Common Name						
Historic/Original Owner	William B Colburn					
Historic Building Use	D/Single Dwelling					
Current Building Use	D/Single Dwelling					
Architect/Engineer/Designer	Rogers & Bonnah					
Builder/Contractor						

Survey Date	12/2020	Recorded By	J. Miller	Agency Report #	
-------------	---------	-------------	-----------	-----------------	--

For SHPO Use Only	SHPO Concurrence?: Y / N	Date:	
-------------------	--------------------------	-------	--

Narrative Architectural Description

Provide a detailed description of the property, including all character-defining features and any accessory resources. This is required for all properties.

A two-story French Eclectic house with a slate hip roof and a shed roof dormer with a ribbon of three casement windows. The main walls are covered in stucco with the dormer being clad in horizontal siding. A two-story flat roof bay window projects from the northeast end of the house. The main door is next to the bay and has a simple lintel/balcony with a metal balustrade. French doors with transoms provide access to the balcony. A wide one-story bay topped with a metal roof is on the northwest end of the building. There are three casement windows directly above the bay. Two brick chimneys are visible.

There is a detached garage at the rear of the property – as the house is non-contributing the garage is as well.

History of the Resource

Provide information on previous owners, land use(s), and construction and alteration dates in a narrative format. This is required for all intensive level surveys, NRPQs, and nominations, and recommended for other identification efforts.

Rogers & Bonnah designed this house for William B. Colburn in 1912. Colburn was the secretary and treasurer of the Detroit Motorbus Company.

Statement of Significance/Recommendation of Eligibility

Provide a detailed explanation of the property's eligibility for the National Register. Include an evaluation under at least one of the four National Register Criteria and one Area of Significance. Include a discussion of the seven aspects of integrity and make a recommendation about eligibility. This is required for all properties.

Due to extensive alterations to the roofline, this house is non-contributing to the historic district.

References

List references used to research and evaluate the individual property. For NRPQ's include copies of key documents.



1965 – courtesy of the Grosse Pointe Historical Society



1977 – courtesy of the Grosse Pointe Historical Society



1979 – courtesy of the Grosse Pointe Historical Society



1983 – courtesy of the Grosse Pointe Historical Society

Michigan SHPO Architectural Properties Identification Form



Property Overview and Location

Street Address	344 Washington				
City/Township, State, Zip Code	Grosse Pointe, MI 48230				
County	Wayne				
Assessor's Parcel #	37 005 08 0016 301				
Latitude/Longitude (to the 6 th decimal point)	Lat: 42.388315	Long: -82.904853			
Ownership	Private <input checked="" type="checkbox"/>	Public-Local <input type="checkbox"/>	Public-State <input type="checkbox"/>	Public-Federal <input type="checkbox"/>	Multiple <input type="checkbox"/>

Property Type

(Insert primary photograph below.)

Building <input checked="" type="checkbox"/> select sub-type below	Structure <input type="checkbox"/>
Commercial <input type="checkbox"/>	Object <input type="checkbox"/>
Residential <input checked="" type="checkbox"/>	
Industrial <input type="checkbox"/>	
Other <input type="checkbox"/>	



Architectural Information

Construction Date	1996	
Architectural Style	Colonial Revival	
Building Form	Rectangular	
Roof Form	Side Gable	
Roof Materials	Asphalt Shingle	
Exterior Wall Materials	Brick	
Foundation Materials	Brick	
Window Materials	Wood	
Window Type	Double hung	
Outbuildings	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
Number/Type:	none	

Eligibility

Individually Eligible	Criterion A <input type="checkbox"/>	Criterion B <input type="checkbox"/>	Criterion C <input type="checkbox"/>	Criterion D <input type="checkbox"/>
Criteria Considerations:	a. <input type="checkbox"/> b. <input type="checkbox"/> c. <input type="checkbox"/> d. <input type="checkbox"/> e. <input type="checkbox"/> f. <input type="checkbox"/> g. <input type="checkbox"/>			
Component of a Historic District	Contributing to a district <input type="checkbox"/>	Non-contributing to a district <input checked="" type="checkbox"/>	Historic District Name	
Not Eligible <input type="checkbox"/>				
Area(s) of Significance	Social history, Architecture			
Period(s) of Significance	1898-1940			
Integrity – Does the property possess integrity in all or some of the 7 aspects?				
Location <input type="checkbox"/>	Design <input type="checkbox"/>	Materials <input type="checkbox"/>	Workmanship <input type="checkbox"/>	Setting <input type="checkbox"/> Feeling <input type="checkbox"/> Association <input type="checkbox"/>
General Integrity:	Intact <input checked="" type="checkbox"/>	Altered <input type="checkbox"/>	Moved <input type="checkbox"/>	Date(s):
Historic Name				
Current/Common Name				
Historic/Original Owner				
Historic Building Use	D/Single Dwelling			
Current Building Use	D/Single Dwelling			
Architect/Engineer/Designer				
Builder/Contractor				

Survey Date	12/2020	Recorded By	J. Miller	Agency Report #	
-------------	---------	-------------	-----------	-----------------	--

For SHPO Use Only	SHPO Concurrence?: Y / N	Date:	
-------------------	--------------------------	-------	--

Narrative Architectural Description

Provide a detailed description of the property, including all character-defining features and any accessory resources. This is required for all properties.

A two-story Colonial Revival with a side gable roof and two cross gables. The cross gables both have gable windows plus two 6-over-6 double hung windows on the upper story and two 9-over-9 double hung on the lower story, all with louvered shutters and limestone sills. A massive balcony is centered on the house, has a simple balustrade of six posts and a lattice arrangement, and is supported by six columns. The balcony is accessed from the second floor via a French door that has multiple sidelights. The main entry has a wide cornice with dentils on the frieze board and is flanked on either side by sidelights. Two gable roof dormers are evenly spaced on the roof directly above the balcony and have 6-over-6 double hung windows.

A brick wall on the south property line (same wall as at 320 Washington) contributes to the district.

History of the Resource

Provide information on previous owners, land use(s), and construction and alteration dates in a narrative format. This is required for all intensive level surveys, NRPQs, and nominations, and recommended for other identification efforts.

Statement of Significance/Recommendation of Eligibility

Provide a detailed explanation of the property's eligibility for the National Register. Include an evaluation under at least one of the four National Register Criteria and one Area of Significance. Include a discussion of the seven aspects of integrity and make a recommendation about eligibility. This is required for all properties.

This house is outside of the period of significance and is non-contributing to the historic district.

References

List references used to research and evaluate the individual property. For NRPQ's include copies of key documents.

Michigan SHPO Architectural Properties Identification Form



Property Overview and Location

Street Address	354 Washington				
City/Township, State, Zip Code	Grosse Pointe, MI 48230				
County	Wayne				
Assessor's Parcel #	37 005 08 0016 302				
Latitude/Longitude (to the 6 th decimal point)	Lat: 42.3885	Long: -82.904942			
Ownership	Private <input checked="" type="checkbox"/>	Public-Local <input type="checkbox"/>	Public-State <input type="checkbox"/>	Public-Federal <input type="checkbox"/>	Multiple <input type="checkbox"/>

Property Type

(Insert primary photograph below.)

Building <input checked="" type="checkbox"/> select sub-type below	Structure <input type="checkbox"/>
Commercial <input type="checkbox"/>	Object <input type="checkbox"/>
Residential <input checked="" type="checkbox"/>	
Industrial <input type="checkbox"/>	
Other <input type="checkbox"/>	



Architectural Information

Construction Date	1918
Architectural Style	Colonial Revival
Building Form	Rectangular
Roof Form	Side Gable
Roof Materials	Asphalt Shingle
Exterior Wall Materials	Brick
Foundation Materials	Brick
Window Materials	Wood
Window Type	Double hung
Outbuildings	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Number/Type:	garage

Eligibility

Individually Eligible	Criterion A <input type="checkbox"/>	Criterion B <input type="checkbox"/>	Criterion C <input type="checkbox"/>	Criterion D <input type="checkbox"/>		
Criteria Considerations:	a. <input type="checkbox"/> b. <input type="checkbox"/> c. <input type="checkbox"/> d. <input type="checkbox"/> e. <input type="checkbox"/> f. <input type="checkbox"/> g. <input type="checkbox"/>					
Component of a Historic District	Contributing to a district <input checked="" type="checkbox"/>	Non-contributing to a district <input type="checkbox"/>	Historic District Name			
Not Eligible <input type="checkbox"/>						
Area(s) of Significance	Social history, Architecture					
Period(s) of Significance	1898-1940					
Integrity – Does the property possess integrity in all or some of the 7 aspects?						
Location <input checked="" type="checkbox"/>	Design <input checked="" type="checkbox"/>	Materials <input checked="" type="checkbox"/>	Workmanship <input checked="" type="checkbox"/>	Setting <input checked="" type="checkbox"/>	Feeling <input checked="" type="checkbox"/>	Association <input type="checkbox"/>
General Integrity:	Intact <input checked="" type="checkbox"/>	Altered <input type="checkbox"/>	Moved <input type="checkbox"/>	Date(s):		
Historic Name						
Current/Common Name						
Historic/Original Owner						
Historic Building Use	D/Single Dwelling					
Current Building Use	D/Single Dwelling					
Architect/Engineer/Designer	John Scott & Company					
Builder/Contractor						

Survey Date	12/2020	Recorded By	J. Miller	Agency Report #	
-------------	---------	-------------	-----------	-----------------	--

For SHPO Use Only	SHPO Concurrence?: Y / N	Date:	
-------------------	--------------------------	-------	--

Narrative Architectural Description

Provide a detailed description of the property, including all character-defining features and any accessory resources. This is required for all properties.

A brick side gabled Colonial Revival with an asphalt shingled roof, boxed cornice returns, and four gable dormers with 6-over-1 windows. There are parapet walls with chimneys on either end of the house. Visible windows are 6-over-1 or 8-over-1, all double-hung, most with louvered shutters. The cornice of the main roofline has small brackets and a wide frieze. There is a portico supported by four wooden columns over a concrete stoop.

One-story tall garage to east of house faces Maumee. Matches style of house contributes to the district.

History of the Resource

Provide information on previous owners, land use(s), and construction and alteration dates in a narrative format. This is required for all intensive level surveys, NRPQs, and nominations, and recommended for other identification efforts.

Designed by John Scott and Company for an unknown client in 1918.

Statement of Significance/Recommendation of Eligibility

Provide a detailed explanation of the property's eligibility for the National Register. Include an evaluation under at least one of the four National Register Criteria and one Area of Significance. Include a discussion of the seven aspects of integrity and make a recommendation about eligibility. This is required for all properties.

Constructed during the period of significance and retains historic and architectural integrity - contributes to the district.

References

List references used to research and evaluate the individual property. For NRPQ's include copies of key documents.



1954 – courtesy of the Grosse Pointe Historical Society




1954 – courtesy of the Grosse Pointe Historical Society



1994 – courtesy of the Grosse Pointe Historical Society



1994 – courtesy of the Grosse Pointe Historical Society (rear of house)



undated – courtesy of the Grosse Pointe Historical Society



undated – courtesy of the Grosse Pointe Historical Society

Michigan SHPO Architectural Properties Identification Form



Property Overview and Location

Street Address	355 Washington				
City/Township, State, Zip Code	Grosse Pointe, MI 48230				
County	Wayne				
Assessor's Parcel #	37 005 08 0027 003				
Latitude/Longitude (to the 6 th decimal point)	Lat: 42.388297	Long: -82.905178			
Ownership	Private <input checked="" type="checkbox"/>	Public-Local <input type="checkbox"/>	Public-State <input type="checkbox"/>	Public-Federal <input type="checkbox"/>	Multiple <input type="checkbox"/>

Property Type

(Insert primary photograph below.)

Building <input checked="" type="checkbox"/> select sub-type below	Structure <input type="checkbox"/>
Commercial <input type="checkbox"/>	Object <input type="checkbox"/>
Residential <input checked="" type="checkbox"/>	
Industrial <input type="checkbox"/>	
Other <input type="checkbox"/>	



Architectural Information

Construction Date	1958	
Architectural Style	Neo-Colonial	
Building Form	Rectangular	
Roof Form	Side Gable	
Roof Materials	Asphalt Shingle	
Exterior Wall Materials	Brick	
Foundation Materials	Brick	
Window Materials	Wood	
Window Type	Double hung	
Outbuildings	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
Number/Type:	none	

Eligibility

Individually Eligible	Criterion A <input type="checkbox"/>	Criterion B <input type="checkbox"/>	Criterion C <input type="checkbox"/>	Criterion D <input type="checkbox"/>
Criteria Considerations:	a. <input type="checkbox"/> b. <input type="checkbox"/> c. <input type="checkbox"/> d. <input type="checkbox"/> e. <input type="checkbox"/> f. <input type="checkbox"/> g. <input type="checkbox"/>			
Component of a Historic District	Contributing to a district <input type="checkbox"/>	Non-contributing to a district <input checked="" type="checkbox"/>	Historic District Name	
Not Eligible <input type="checkbox"/>				
Area(s) of Significance	Social history, Architecture			
Period(s) of Significance	1898-1940			
Integrity – Does the property possess integrity in all or some of the 7 aspects?				
Location <input type="checkbox"/>	Design <input type="checkbox"/>	Materials <input type="checkbox"/>	Workmanship <input type="checkbox"/>	Setting <input type="checkbox"/> Feeling <input type="checkbox"/> Association <input type="checkbox"/>
General Integrity:	Intact <input checked="" type="checkbox"/>	Altered <input type="checkbox"/>	Moved <input type="checkbox"/>	Date(s):
Historic Name				
Current/Common Name				
Historic/Original Owner				
Historic Building Use	D/Single Dwelling			
Current Building Use	D/Single Dwelling			
Architect/Engineer/Designer				
Builder/Contractor				

Survey Date	12/2020	Recorded By	J. Miller	Agency Report #	
-------------	---------	-------------	-----------	-----------------	--

For SHPO Use Only	SHPO Concurrence?: Y / N	Date:	
-------------------	--------------------------	-------	--

Narrative Architectural Description

Provide a detailed description of the property, including all character-defining features and any accessory resources. This is required for all properties.

A two-story side gabled neo-Colonial with asphalt shingles It has two “through the cornice” gabled dormers with 6-over-6 double hung windows. A cross gable projects off the front of the house. A pair of large double hung windows is below the cross gable. A front porch is covered by a shed roof supported by three boxed posts and covers the main entrance and a large window with shutters. Wall covering on the lower level is brick with the upper level covered in wooden shingles. A garage off the western façade has a side gable and a large gable wall dormer with two windows. A shed roof supported by brackets is above the garage door.

History of the Resource

Provide information on previous owners, land use(s), and construction and alteration dates in a narrative format. This is required for all intensive level surveys, NRPQs, and nominations, and recommended for other identification efforts.

Statement of Significance/Recommendation of Eligibility

Provide a detailed explanation of the property’s eligibility for the National Register. Include an evaluation under at least one of the four National Register Criteria and one Area of Significance. Include a discussion of the seven aspects of integrity and make a recommendation about eligibility. This is required for all properties.

This house is outside of the period of significance and is non-contributing to the historic district.

References

List references used to research and evaluate the individual property. For NRPQ’s include copies of key documents.



1973 – courtesy of the Grosse Pointe Historical Society



1973 – courtesy of the Grosse Pointe Historical Society



1980 – courtesy of the Grosse Pointe Historical Society

Michigan SHPO Architectural Properties Identification Form



Property Overview and Location

Street Address	359 Washington				
City/Township, State, Zip Code	Grosse Pointe, MI 48230				
County	Wayne				
Assessor's Parcel #	37 005 08 0027 001				
Latitude/Longitude (to the 6 th decimal point)	Lat: 42.38837	Long: -82.905212			
Ownership	Private <input checked="" type="checkbox"/>	Public-Local <input type="checkbox"/>	Public-State <input type="checkbox"/>	Public-Federal <input type="checkbox"/>	Multiple <input type="checkbox"/>

Property Type

(Insert primary photograph below.)

Building <input checked="" type="checkbox"/> select sub-type below	Structure <input type="checkbox"/>
Commercial <input type="checkbox"/>	Object <input type="checkbox"/>
Residential <input checked="" type="checkbox"/>	
Industrial <input type="checkbox"/>	
Other <input type="checkbox"/>	



Architectural Information

Construction Date	1953	
Architectural Style	Mid-Century Modern	
Building Form	Irregular	
Roof Form	Side Gable	
Roof Materials	Asphalt Shingle	
Exterior Wall Materials	Brick, Horizontal Siding	
Foundation Materials	Brick	
Window Materials	Wood	
Window Type	Sliding	
Outbuildings	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
Number/Type:	none	

Eligibility

Individually Eligible	Criterion A <input type="checkbox"/>	Criterion B <input type="checkbox"/>	Criterion C <input type="checkbox"/>	Criterion D <input type="checkbox"/>		
Criteria Considerations:	a. <input type="checkbox"/> b. <input type="checkbox"/> c. <input type="checkbox"/> d. <input type="checkbox"/> e. <input type="checkbox"/> f. <input type="checkbox"/> g. <input type="checkbox"/>					
Component of a Historic District	Contributing to a district <input type="checkbox"/>	Non-contributing to a district <input checked="" type="checkbox"/>	Historic District Name			
Not Eligible <input type="checkbox"/>						
Area(s) of Significance	Social history, Architecture					
Period(s) of Significance	1898-1940					
Integrity – Does the property possess integrity in all or some of the 7 aspects?						
Location <input type="checkbox"/>	Design <input type="checkbox"/>	Materials <input type="checkbox"/>	Workmanship <input type="checkbox"/>	Setting <input type="checkbox"/>	Feeling <input type="checkbox"/>	Association <input type="checkbox"/>
General Integrity:	Intact <input checked="" type="checkbox"/>	Altered <input type="checkbox"/>	Moved <input type="checkbox"/>	Date(s):		
Historic Name						
Current/Common Name						
Historic/Original Owner						
Historic Building Use	D/Single Dwelling					
Current Building Use	D/Single Dwelling					
Architect/Engineer/Designer						
Builder/Contractor						

Survey Date	12/2020	Recorded By	J. Miller	Agency Report #	
-------------	---------	-------------	-----------	-----------------	--

For SHPO Use Only	SHPO Concurrence?: Y / N	Date:	
-------------------	--------------------------	-------	--

Narrative Architectural Description

Provide a detailed description of the property, including all character-defining features and any accessory resources. This is required for all properties.

A story-and-a-half side gabled asphalt shingled Mid-Century Modern residence with a large brick chimney slightly off-center of the main elevation. Two shed dormers with 6-over-6 double hung windows and horizontal siding are on the eastern end of the house. The house is covered in brick up to the roof line, then covered in horizontal siding in the gables. The main elevation features a pair of projecting forward facing gables, with the smaller (more prominent) having a gable window with shutters and three tall sliding windows framed by pilasters on the main level. This gable is covered with horizontal siding and features the main entrance to the house on the western side. The second, taller gable is covered in horizontal siding down to roughly knee high, then switches to brick. The west elevation has a ribbon of three double hung windows in the gable and two bay windows with conical roofs.

History of the Resource

Provide information on previous owners, land use(s), and construction and alteration dates in a narrative format. This is required for all intensive level surveys, NRPQs, and nominations, and recommended for other identification efforts.

Statement of Significance/Recommendation of Eligibility

Provide a detailed explanation of the property's eligibility for the National Register. Include an evaluation under at least one of the four National Register Criteria and one Area of Significance. Include a discussion of the seven aspects of integrity and make a recommendation about eligibility. This is required for all properties.

This house is outside of the period of significance and is non-contributing to the historic district.

References

List references used to research and evaluate the individual property. For NRPQ's include copies of key documents.